

AUTOLAND[®]

S C I E N T E C H

Autoland Utility:

Updating File Manager

Introduction

This slide will help an existing member update their Autoland Utility program with the newest version of File Manager.

Prerequisites:


- Registered member
- Autoland Utility installed
- Administrative rights on PC
 - Logged in as Admin

Members Section



iSCAN II wt

Visit our homepage
www.autolandscientechnusa.com



Log into
the Members section **

** Complete Member registration for login credentials

Browse to Downloads

MEMBER
AUTOLAND
S.C.I.E.N.T.E.C.H

Home Products About Tech Support Human Resources **Member** Forums Contact

Autoland Scientech USA(Agency)

Current Date	2016-10-22	Agency	Autoland Scientech USA
Contact Person	AUTOLAND USA	ID	
Tel		Fax	15123363731
Email		Company Address	1001 Cypress Creek Rd. Suite 101 Cedar Park, TX 78613

[Modify Member Information](#) [Logout](#)

- iSCAN-II wt
- iSCAN-II
- VeDiS-II
- D91/VeDiS/D51
- OB91-VM
- Tools Download & ePaper**

Tools, Downloads & ePapers

LOCATION: >MEMBER
AUTOLAND
S.C.I.E.N.T.E.C.H

Home Products About Tech Support Human Resources **Member** Forums Contact

Agency: Autoland Scientech USA

Contact Person	AUTOLAND USA	ID	
Tel		Fax	15123363731
Email		Company Address	1001 Cypress Creek Rd. Suite 101 Cedar Park, TX 78613

[Modify Member Information](#) [Logout](#)

iSCAN-II wt

Tools Download & ePaper

Software Download Tools & Instructions	Read ePaper
--	-----------------------------

iSCAN-II

VeDiS-II

D91/VeDiS/D51

OB91-VM

Tools Download & ePaper

Software downloads

Find the latest version

The screenshot shows the website's navigation menu with 'Member' highlighted in red. Below the menu is a table titled 'Software Download' with two columns: 'Software Name' and 'Download'. The table lists various software versions, and the 'File Manager V8.07 iSCAN-II wt / VeDiS-II / PS-Module III (English)' row is highlighted with a red box. A red arrow points to the download icon in this row.

Software Name	Download
Autoland Utility V1.1.9	
AutoUpdate V3.03SP1 USEN for iSCAN-II wt / iSCAN-II / VeDiS-II	
PSM3_driver_v4.inf (iSCAN-II / VeDiS-II / PSM3 USB Driver)	
PSM3_Patch_for_XP_SP3.ZIP (Windows XP SP3 Correction)	
File Manager V8.07 for iSCAN-II wt / VeDiS-II / PS-Module III (Traditional Chinese)	
File Manager V8.07 for iSCAN-II wt / VeDiS-II / PS-Module III (Simplified Chinese)	
File Manager V8.07 iSCAN-II wt / VeDiS-II / PS-Module III (English)	
File Manager V8.07 iSCAN-II wt / VeDiS-II / PS-Module III (Japanese)	
autoload setup (automatic software download tool)	
PL-2303 Driver (For PS-Module I & II)	
PC-Scanner V5.00 for iSCAN-IIwt / VeDiS-II	
PC-Scanner V2.11 for D91 / VeDiS	
PC-Scanner for BMW GT2 V1.11	
IMS2-MB Add-On V4.05.exe (IMS2-MB Utility)	
IMS2-VASS Add-On V2.04.exe (IMS2 VASS Utility)	
IMS2-VASS ODIS AddOn V2.00	

Select your language preference and Click on the download icon

Download File Manager




Google Chrome
Show in folder after download
completes




Internet Explorer
Click Save, then Open in Folder

** To continue, you will need to know the location of the file you are saving.

Locate and Rename




Locate your download. (Default location is the Downloads folder)



Rename the download (Use File_manager_USEN)

****Autoland Utility is case sensitive. Misspelling the file name will result in an error finding/launching File Manager**


Update Autoland Utility directory



Move the file to folder PSModule (default location is the C:\ drive)

**** Autoland Utility will only search this location for versions of File Manager**

Overwrite Previous Version



Choose "Move and Replace."

Conclusion

- Launch Autoland Utility and click on File Manager to ensure you have completed the steps correctly.
- If File Manager does not launch
 - Ensure the download is located in the right directory
 - [C:\PSModule]
 - Ensure the filename is spelled exactly
 - [File_manager_USEN]
- If File Manager launches in a different language
 - Repeat the steps from the beginning.
 - Locate your preferred language on the list of the downloads.
- Please ensure the scanner is powered off and **ONLY** connected via USB

**** If you are still experiencing issues: Take a screenshot of the error message and contact Autoland Scientech USA, Inc. at (512)336-5152**