AUTOLAND S C I E N T E C H

How to update your scanner

Before you begin

- You must be registered as an Autoland Member
 - For a detailed guide please review 'How to register as a member'
- Your scanner must be registered to you.
 - For a detailed guide please review 'How to register your scanner'
- Autoland Utility must be installed on the PC
 - For a detailed guide please review 'Autoland Utility Setup'
- Autoland Utility has been updated with the latest version of File Manager
 - For a detailed guide please review 'Updating File Manager'
- Please ensure the scanner is powered off and ONLY connected via USB during this process.

Launch File Manager



Reading Scanner

¢	🔅 File Manager V8.07			1			X
	File Manager Download	list Print					
	Selected files for instal	I		Files listed in iSCAN-I	I/PS-Module		
L		Vehicle brand Version Information	Space		Vehicle brand	Version Information	Space
L							
L							
L							
L							
L							
L							
L							
		_					
		Please w	ait				
		Getti	ng PS-Module file alloca	tion table			
	Required space:			Free space:	Used space:	Re-Initialize	
	LOAD			S/N: 00 03 00	03 Status: Detecting	Delete LOG	
				BURN Program	nming		
				Checkir	ıg		
	Please co	nnect the USB cable to the SCANNE	R/PS-Module and th	e PC's USB port			
(WARNING: Do Not POWER ON scanner while connected.)							
	S/N ·	00.03.00.03				_	_
Status : Detecting Allow File Manager a few						rew	
				o into to	wood t		
Ľ	Getting PS-Module	e file allocation table Please wait>	mome	ents to	read	ne mes	on you
					scann	or	
					Juaill		

Scanner not found

Required space:	BURN Programming BURN Programming
Note: Connecting Please connect the USB cable to the SCANNER/PS-Module and the (WARNING: Do Not POWER ON scanner while connected.) S/N : S/N : Status :	e PC's USB port.
Device not EXIST	

- If you see 'Device not EXIST' at any point you will need to plug the scanner into the computer
- If the unit is already connected, simply disconnect the USB cable for a couple seconds and reconnect

Click on Download List tab

Double click on New order or Double click here for new order.

😂 File Ma	File Manager V8.04								
File Mana	File Manager Download list Print								
	PSM S/N	Status	Download progress	Next Step					
	New order			Double click here for new order					

	New order request	
	if you want to request a new order, please input PSM number(8 digitals, ex. 00018000):	
	OK Cancel	
Informat	tion	×
1	PSM_NO:000 ,do you want to Request a new or	der?
	Yes <u>N</u> o	

When prompted, enter your serial number (in the 000xxxx format) and confirm your order.

Downloading Order

File Mana	ger Downloa	d list Print		
	PSM S/N	Status	Download progress	Next Step
	000	Order accepted(10/17/2014 11:47:18 AM)		Wait for prepare files
	New order			Double click here for new order

Your order will be accepted by the server and in 5-10 minutes you will start seeing the files being downloaded. Make sure and wait for the download to get to 100%.

File Mana	iger Do	wnload	list Print			
	PSM S	/N S	itatus		Download progress	Next Step
	000	D	Downloadin	g(10/17/2014 11:53:18 AM)	9/45(20%)	Downloading(898)
	New or	rder				Double click here for new order

* If your order does not fetch anything and instead shows 0/0 (100%) just create a new order and it will eventually start fetching files.

File Manager Download list Print							
]	PSM S/N	Status			Download progress	Next Step	
	000	Download F	inished(10/3/2014 1	1:53:24 PM)	0/0(100%)	Program(Double click)	
]	New order					Double click here for new order	
			New order request if you want to request a new PSM number(8 digitals, ex. 1 000	order, please input 00018000): Cancel			
				Information PSM_NO:0	00 ,do you want to Request a t Yes <u>N</u> o	new order?	

* For WT owners:

If it looks like it's stuck at 98%. Do not worry, the last file to download is the biggest one (BMW Encoding Database) so it takes longer to download - it will eventually get to 100%.

File Mana	File Manager Download list Print						
	PSM S/N	Status	Download progress	Next Step			
	000	Downloading(11/13/2014 11:40:58 AM)	69/70(98%)	Downloading(998)			
	New order			Double click here for new order			

6. When the download is done, double click on **Program (Double click)** to start the update.

File Mana	ger Downloa	d list Print		
	PSM S/N	Status	Download progress	Next Step
	000	Download Finished(10/17/2014 12:05:13 PM)	45/45(100%)	Program(Double click)
	New order			Double click here for new order



Confirm you want to start the update.



* If you see this pop-up, unplug your scanner, plug it back in and repeat the procedure.

Programming in progress

File Manager V8.07							
File Manager Download	1 list Print						
Selected files for insta	II			Files listed in iSCAN-II/PS-Module			
ROOT EUROPEAN BMW PKG BMW PKG BMW DL BMW BMW BMW BMW BMW BMW CBMW CE38/E CE46/4 F Ser EE6/2	Vehicle brand [EUROPEAN] [USA] [ASIAN] [Latin America] [AUSTRALIA] [IMS2] [J2534] [OBDII] FORD NISSANINFINITI OPEL-BR	Version Information 29 files 5 files 18 files 4 files 3 files 15 files 5 files 2 files 2015:12SP1 MXSP FORD O 2015:12SP2 MXSP 2012:02 MXSP	Space 5218Units 1192Units 2339Units 1057Units 510Units 77Units 20Units 18Units 221Units 58Units 18Units	BROOT BRW PKG BMW PKG BMW PKG BMW D BMW BMW BMW BMW BMW C E38/ E46(F Se E66/	Vehicle brand [EUROPEAN] [USA] [ASIAN] [Latin America] [AUSTRALIA] [IMS2] [J2534] [OBDII] SYSTEM FORD NISSAN/INFINITI	Version Information 29 files 5 files 18 files 3 files 15 files 5 files 5 files 1 files V3.06 USEN 2015.12SP1 MXSP FORD 2015.12SP2 MXSP	Space 5218Un 1192Un 2339Un 1057Un 510Units 77Units 20Units 9Units 10Units 2110Units 500Units 9Units 50Units 50Units 50Units
- Cesre - Eesre - MINI - FIAT LANCL - FORD PKG - LAND ROVE - MERCEDES - OPEL VAUS - PORSCHE I - VW AUDI S - USA - GM PKG - ASIAN	SYSTEM VASS	V3.06 USEN 2015.12SP2 MXSP	10Units 760Units	- Lesy - Eesy - FIAT LANC - FORD PKG - LAND ROV - MERCEDE - OPEL VAU - PORSCHE - VW AUDI S - USA - GM PKG - ASIAN	OPEL-BR VASS	2012.02 MXSP 2015.12SP2 MXSP	18Units 760Units
Required space:	OUnit	_		Free space: 231276 S/N: 00 03 00 BURN Program Chacking Chacking	SUnit Used space: 03 Status: Devic	Re-Initialize e EXIST Delete	
Note: Programming Select file and click the [BURN] button to burn the software to the iSCAN-II/cartridge. Wait until the status monitor indicates that the select software has been successfully downloaded to the iSCAN-II/cartridge then remove the USB cable.							
Programming Please wait> Files remaining to be programmed will appear in re							

90

Programming complete

File Manager V8.07							
File Manager Download list Print							
Selected files for install	Files listed in iSCAN-II/PS-Module						
Vehicle brand Version Information Space	E-ROOT Vehicle brand Version Information	Space					
Information ES Program OK! OK	EUROPEAN BMW PKG BMW PKG BMW PKG BMW D BMW BMM BMM	5218Units 1192Units 2339Units 1057Units 510Units 77Units 20Units 9Units 10Units 221Units 58Units 18Units 760Units					
Required space:	S/N: 00 03 00 03 Status: Device EXIST Delete LOG						
	BURN Programming						
	Checking						
Note: Programming Select file and click the [BURN] button to burn the software to the iSCAN-II/cartridge. Wait until the status monitor indicates that the select software has been successfully downloaded to the iSCAN-II/cartridge then remove the USB cable.							
Program OK! Program OK! When 'Program OK' appears click							

er

Conclusion

- Download times will vary based on your connection speed and subscription type
- Programming times will vary based on your PC Performance
- If you suspect software issues
 - Please perform Re-initializing steps as detailed in the last slide
 - ie. Duplicate Files, Scanner was disconnected while programming, computer was restarted while programming scanner.

****IMPORTANT: Do NOT press the Re-Initialize button for any other reason**

• This will wipe out all software on the unit.

** If you are still experiencing issues: Take a screenshot of the error message and contact Autoland Scientech USA, Inc. at (512)336-5152

File Tree

Files listed in iSCAN-II	/PS-Module		
E. ROOT	Vehicle brand	Version Information	Space
EUROPEAN	SavedScreen-1.raw4	1	3Units
⊞ USA	SavedScreen-2.raw4		3Units
⊞ ASIAN	SavedScreen-3.raw4		3Units
Latin America	SavedScreen-4.raw4		3Units
⊕ AUSTRALIA			
1052			
OBDII			
PrintScreen			
SYSTEMV3.0	Information		
Session 1		1	
	Remove2 items??		
	<u>Yes</u> <u>N</u> o		
	1		
Free space: 231264	Unit Used space: 11501Unit	Re-Initialize	
S/N: 00 03 00	03 Status: Device EXIST	Delete LOG	
BURN Program	nming		
Checkin	ıg		

- Logs, Screenshots or complete folders can be removed
 - Select one or more files and click 'Delete' at the bottom.
 - Then, click Yes to confirm

 You should see the following error if the system file was selected.
 *** If the system file has been deleted continue to the last slide to Re-initialize



Re-initializing



** If the system file has been removed the scanner MUST be re-initialized